PATENT

PE 400862.023241

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)
Takehiko IWANAGA et al.	Examiner: J. B. Lieu
Application No.: 10/662,471	) Group Art Unit: 2636
Filed: September 16, 2003	;
For: POWER MONITORING UNIT, CONTROL METHOD THEREFOR, AND EXPOSURE APPARATUS	: ) October 4, 2005 : )
U.S. Patent No. 6,909,372 B2	; )
Issued: June 21, 2005	: )

Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

**Attention: Certificate of Correction Branch** 

Certificate
0CT 1 1 2005
of Correction

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of U.S. Patent and Trademark Office mistakes and mistakes of a minor nature which are not the fault of the Patent and Trademark Office.

10/06/2005 BABRAHA1 00000051 6909372

01 FC:1811

100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentees

Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SEW/eab

DC\_MAIN 217657v1

# Staple Here Only!

# UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,909,372 B2

DATED

: June 21, 2005

INVENTOR(S): Takehiko IWANAGA et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 17:

Line 33, "comprises" should read -- comprises: --.

Line 47, "comprises" should read -- comprises: --.

### COLUMN 18:

Line 13, "monitor" should read -- monitors --.

Line 21, "comprises" should read -- comprises: --.

Line 36, "comprises" should read -- comprises: --.

#### COLUMN 19:

Line 12, "comprises" should read -- comprises: --.

Line 14, "failures" should read -- failures; --.

Line 20, "comprises" should read -- comprises: --.

Line 46, "comprises" should read -- comprises: --.

Line 49, "failures" should read -- failures; --.

Line 53, the right margin should be closed up.

#### COLUMN 20:

Line 4, "comprises" should read -- comprises: --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,909,372 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page